

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 8/9/0 Property Name San Juan 32-5 W	Operator f	Energen (esour cesapi #30-0_	3924295
Property Name Sin Juan 32-5 W	ell No. 102	Location: Unit <u>K</u> Section <u>24</u> Το	ownship321/Range 6 W
Well Status (Shut-In or Producing) T	ubing 70	Intermediate 1/14 Casing 70 Bra	idenhead D
OPEN BRADENHEAD AND INTERM	MEDIATE TO	ATMOSPHERE INDIVIDUALLY FO	OR 15 MINUTES EACH
PRESSURES: TIME BRADENHEAD INTERMEDIAT	E CASING	BRADENHEA FLOWED	AD INTERMEDIATE FLOWED
5 minutes O N/H	70	Steady Flow	
10 minutes	70	Surges	
15 minutes	70	Down to Nothing	
20 minutes		Nothing	N/A
25 minutes		Gas	
30 minutes		Gas & Water	
		Water	
If bradenhead flowed water, check all of the	e descriptions t	that apply below:	3617 18 1920 2723
CLEAR FRESH SALTY SULFUR BLACK PECEUR			
5 MINUTE SHUT-IN BRADENHEAD REMARKS:	0_	SULFUR BLACK BLACK BLACK BLACK BLACK BLACK BLACK STORTON OF THE STORTON	5 - 60/
			551-123
$C_{\alpha}(Q_{\alpha} - Q_{\alpha}) = 1$			
Senior Lease Oper (Position)	rator	Witness	
E-mail address	1		