## NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

## **BRADENHEAD TEST REPORT**



(Submit 2 copies to above address)

			(0000			,			
Date of Test	6-2	∼ 2010 Operator		Ener	Energen Resources			3003924402	
Property Nam			CAS 26 A 2	Locatio	on: Unit B	Section 26 To	ownship 32	Range 5	
		(Well Name	and Number)						
Pressure (Sh	ut-in or Proc	ducing	Tubing	3_5 Interme	ediate	Casing <u>Q</u>	S Bradenh	ead	
OPEN	N BRADENHI	EAD AND	INTERMEDIA	TE TO ATMOS	PHERE IND	IVIDUALLY FOR	15 MINUTES E	ACH	
	Bradenhead			Interme	ediate		Bradonhoad	Intermediate	
<u>Time</u>	BH Blowdown	Casing	Intermediate	Intermediate	Casing		Flowed	Flowed	
5 minutes	Blowdown	Monitor	Monitor	Blowdown	Monitor	Steady Flow	NO		
10 minutes		98			-	Surges	NO		
15 minutes		97		<del></del>		Down to Nothing	NA	·	
20 minutes		98	_			No Flow	1/0		
25 minutes		00		-	<u> </u>	Gas	No		
30 minutes	0	47				Gas and Water	No		
5 minute SI		635	**************************************			Water	10		
		vater, che	Sa	escriptions tha	4		ck <i>NB</i>		
5 Minute S	<b>hut-in</b> B	radenhea		Intermediat					
REMARKS:	Bred	en her	id Was	s at e	s th	rough the l	hole tes	4.	
						1891 1991	044		
						487897	\$ 19 to		
						P TIE	<b>か</b> ない		
Ву	w				itness	To au	Alla (5) =\		
	· · · · · · · · · · · · · · · · · · ·	(Positior	n)			E CONS	DIV. DIST. 3	?/	
		(. 55,50	•1			ૄ <sup>૾</sup> ્રે<્	MOCD Test Area:	C 73	