



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-24-2010 Operator Energen Resources API # 3003924447

Property Name CARRACAS UNIT 14 A 13 Location: Unit M Section 14 Township 32 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 28 Intermediate Casing 65 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>	<u>68</u>				Steady Flow <u>0</u>	
10 minutes	<u>0</u>	<u>65</u>				Surges <u>0</u>	
15 minutes	<u>0</u>	<u>65</u>				Down to Nothing <u>0</u>	
20 minutes	<u>0</u>	<u>63</u>				No Flow <u>0</u>	
25 minutes	<u>0</u>	<u>69</u>				Gas <u>0</u>	
30 minutes	<u>0</u>	<u>66</u>				Gas and Water <u>0</u>	
5 minute SI	<u>0</u>	<u>65</u>				Water <u>0</u>	

If bradenhead flowed water, check all of the descriptions that apply below:


Clear NA Fresh NA Salty NA Sulfur NA Black NA

5 Minute Shut-in Bradenhead 0 Intermediate

REMARKS: Test was 0 through out the complete
test

By

[Signature]
Lease operator
(Position)



NMOCD Test Area: C