



# NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

## BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-25-2010 Operator Energex Resources API # 3003924510

Property Name CARRACAS UNIT 27 B 12 Location: Unit L Section 27 Township 32 Range 4  
(Well Name and Number)

Pressure (Shut-in or Producing) Producing Tubing 0 Intermediate N/A Casing 47# Bradenhead 0#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0 <sup>h</sup>	47#	N/A	N/A	N/A	Steady Flow	
10 minutes	0	47#				Surges	
15 minutes	0	47#				Down to Nothing	
20 minutes	0	47#				No Flow	✓
25 minutes	0	47#				Gas	
30 minutes	0	47#				Gas and Water	
5 minute SI	0 <sup>h</sup>	62#	✓	✓	✓	Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear \_\_\_\_\_ Fresh \_\_\_\_\_ Salty \_\_\_\_\_ Sulfur \_\_\_\_\_ Black \_\_\_\_\_

5 Minute Shut-in Bradenhead 0<sup>h</sup> Intermediate N/A

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Richard Heale  
Sr Lease Operator  
(Position)

Witness \_\_\_\_\_

