

## NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test			Operator —	Energ	Energen Resources			3003924519	
Property Name			UNIT 26 B 13	Locatio	Location: Unit M		Fownship 32	Range 4	
Pressure (Shu	t-in or Prod	ducing)	Tubing	59 <sup>₩</sup> _ Interme	diate n	A Casing <u>l</u> a	Bradenl	nead of	
OPEN	BRADENH	EAD AND	INTERMEDIA	TE TO ATMOSE	PHERE IND	IVIDUALLY FOR	15 MINUTES I	EACH	
	E	Bradenhe	ad	Interme	Intermediate		Pradonhoad	Intermediate	
<u>Time</u>	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed	
5 minutes	0#	(co#	۸۱۵	Ala	1/A	Steady Flow	/		
10 minutes	40	(60)	- A/r		1111	Surges	8		
15 minutes	D ₩	(33				Down to Nothing			
20 minutes	0 H	lso				No Flow	۱ <u> </u>		
25 minutes	0#	Coj				Gas	S		
30 minutes	0 F	(W)				Gas and Wate	r		
5 minute SI	04	1104				Wate	r		
If bradenhea	ad flowed v	vater, che	eck all of the de	escriptions tha	t apply bel	ow:			
Clear	F	resh _	Sal	ty	Sulfur	BI	ack 112 <i>13</i> 7	_	
5 Minute Sho	ut-in B	radenhea	d <u>O</u> #	Intermediat	n/a-	2345 8000 8000 BI	ECEIVED TO THE PROPERTY OF THE	19202	
						Oil Co	ONS. DIV. DIST. 3	2027	
	· · · · · · · · · · · · · · · · · · ·					(Sec. )	7,00	/	
				,			8572.25.25.40. V	<u></u>	
By Miche	el Houp Lesse O			Wi	tness				
Sc	lesse 0	persta	<u> </u>						
		(Positio	ר)						