



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6/1/10 Operator Energen Resources API # 3003924651

Property Name CARRACAS UNIT FR 106 Location: Unit H Section 23 Township 32 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 90 Intermediate N/A Casing 80 Bradenhead 60

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>0</u>	<u>80</u>				Steady Flow		
10 minutes	<u>0</u>	<u>80</u>				Surges		
15 minutes	<u>0</u>	<u>75</u>				Down to Nothing	<u>X</u>	
20 minutes	<u>0</u>	<u>80</u>				No Flow		
25 minutes	<u>0</u>	<u>80</u>				Gas		
30 minutes	<u>0</u>	<u>80</u>				Gas and Water		
5 minute SI	<u>0</u>	<u>82</u>				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS:

Braden head blew down immediately, and never
any more pressure.

By [Signature]
Lease Operator III
(Position)

Witness

