



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6/1/10 Operator Energen Resources API # 3003924719

Property Name CARRACAS UNIT PC 201 Location: Unit G Section 22 Township 32 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 90 Intermediate N/A Casing 41 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>0</u>	<u>41</u>	<u>N/A</u>			Steady Flow		
10 minutes	<u>0</u>	<u>41</u>				Surges		
15 minutes	<u>0</u>	<u>41</u>				Down to Nothing		
20 minutes	<u>0</u>	<u>41</u>				No Flow	<u>X</u>	<u>N/A</u>
25 minutes	<u>0</u>	<u>41</u>				Gas		
30 minutes	<u>0</u>	<u>41</u>				Gas and Water		
5 minute SI	<u>0</u>	<u>45</u>				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS:

By [Signature] Witness
Lease Operator III
(Position)

