



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/24/10 Operator Energen Resources API # 3003924724

Property Name CARRACAS UNIT 12 B 16 Location: Unit P Section 12 Township 32 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 28 Intermediate N/A Casing 28 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	0	28	N/A			Steady Flow		N/A
10 minutes	0	28				Surges		
15 minutes	0	28				Down to Nothing	X	
20 minutes	0	28				No Flow		
25 minutes	0	28				Gas		
30 minutes	0	28				Gas and Water		
5 minute SI	0	30				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS:

Slight blow on first blowdown, but not enough to register

By App Hame
Lease Operator III
(Position)

Witness _____

