



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7/7/10 Operator Energen Resources API # 3003925879

Property Name SAN JUAN 32 5 UNIT 9M Location: Unit I Section 30 Township 32 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 82 Intermediate 0 Casing 120 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>0</u>	<u>120</u>	<u>0</u>	<u>0</u>		Steady Flow		
10 minutes	<u>0</u>	<u>120</u>	<u>0</u>	<u>0</u>		Surges		
15 minutes	<u>0</u>	<u>120</u>	<u>0</u>	<u>0</u>		Down to Nothing		
20 minutes						No Flow	<u>✓</u>	<u>✓</u>
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI						Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate 0

REMARKS:

By Alan Kirk Witness _____
Senior Lease Operator
(Position)

