



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7/16/10 Operator Energen Resources API # 3003925901

Property Name SAN JUAN 32 5 UNIT 6A Location: Unit D Section 25 Township 32 Range 6
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 150 Intermediate 0 Casing 154 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Intermediate Flowed Flowed	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	154	0	0	154	Steady Flow	
10 minutes	0	154	0	0	154	Surges	
15 minutes	0	154	0	0	154	Down to Nothing	
20 minutes						No Flow	✓
25 minutes						Gas	✓
30 minutes						Gas and Water	
5 minute SI						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____

5 Minute Shut-in Bradenhead 0 Intermediate 0

REMARKS:

By Alan Kirk Witness _____
Senior Lease Operator
(Position)

