

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	8/5/10		Operator –	Energ	Energen Resources		.PI# 30	3003926156	
		2 5 UNIT 17R and Number)	Locatio	Location: Unit E		ownship 32	Range 6		
Pressure (Shut-in or Producing) Tubing 185 Intermediate 10 Casing 190 Bradenhead 0									
OPEN	BRADENH	EAD AND	INTERMEDIA	TE TO ATMOSI	PHERE INDI	VIDUALLY FOR 1	15 MINUTES	EACH	
Time 5 minutes 10 minutes 15 minutes 20 minutes 25 minutes 30 minutes 5 minute SI	BH Blowdown	Casing Monitor 190 190 190	Intermediate Monitor	Intermediate Blowdown O O	Casing Monitor 190 190	Steady Flow Surges Down to Nothing No Flow Gas Gas and Water Water	Flowed	Intermediate Flowed	
If bradenhead flowed water, check all of the descriptions that apply below: Clear									
	ion fi		Oper		tness				