



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7/23/10 Operator Energex Resources API # 3003926317

Property Name SAN JUAN 30 4 UNIT 46 Location: Unit H Section 8 Township 30 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 300 Intermediate N/A Casing 310 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>No blow</u>	<u>315</u>	<u>N/A</u>	<u>N/A</u>		Steady Flow		
10 minutes	<u>No blow</u>	<u>320</u>	<u>N/A</u>	<u>N/A</u>		Surges		
15 minutes	<u>No blow</u>	<u>325</u>	<u>N/A</u>	<u>N/A</u>		Down to Nothing		
20 minutes						No Flow	<u>X</u>	
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI						Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate N/A



REMARKS:

By Witness _____
(Position)