



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-25-2010 Operator Energen Resources API # 3003926474

Property Name CARRACAS 2A 11 Location: Unit K Section 2 Township 31 Range 5  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 0 Intermediate      Casing 93 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>0</u>	<u>93</u>				Steady Flow	<u>NO</u>	
10 minutes	<u>0</u>	<u>91</u>				Surges	<u>NO</u>	
15 minutes	<u>0</u>	<u>90</u>				Down to Nothing	<u>NO</u>	
20 minutes	<u>0</u>	<u>90</u>				No Flow	<u>NO</u>	
25 minutes	<u>0</u>	<u>90</u>				Gas	<u>NO</u>	
30 minutes	<u>0</u>	<u>93</u>				Gas and Water	<u>NO</u>	
5 minute SI	<u>0</u>	<u>93</u>				Water	<u>NO</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear      Fresh      Salty      Sulfur      Black     

5 Minute Shut-in Bradenhead 0 Intermediate     

REMARKS:

From the Beginning of Braden head test

By

[Signature]  
Lease operator  
(Position)

Witness

