



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-25-2010 Operator Energen Resources API # 3003926475

Property Name CARRACAS 19 B 4 Location: Unit D Section 19 Township 32 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 20 Intermediate Casing 38 Bradenhead

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead Intermediate Flowed Flowed	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor			
5 minutes	<u> </u>	<u>37</u>				Steady Flow	<u>NO</u>	
10 minutes	<u> </u>	<u>38</u>				Surges	<u>NO</u>	
15 minutes	<u> </u>	<u>38</u>				Down to Nothing	<u>NO</u>	
20 minutes	<u> </u>	<u>38</u>				No Flow	<u>NO</u>	
25 minutes	<u> </u>	<u>37</u>				Gas	<u>NO</u>	
30 minutes	<u> </u>	<u>38</u>				Gas and Water	<u>NO</u>	
5 minute SI	<u> </u>	<u>38</u>				Water	<u>NO</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead Intermediat

REMARKS:

 on Braden head from the Beginning to the
end of the test

By

[Signature]
Lease operator

(Position)

Witness

