



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7/26/10 Operator Energen Resources API # 3003927270

Property Name SAN JUAN 32 5 UNIT 100S Location: Unit F Section 23 Township 32 Range 6
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 320 Intermediate N/A Casing 320 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>	<u>320</u>	<u>N/A</u>	<u>N/A</u>			
10 minutes	<u>0</u>	<u>320</u>					
15 minutes	<u>0</u>	<u>320</u>					
20 minutes							
25 minutes							
30 minutes							
5 minute SI							

Steady Flow		
Surges		
Down to Nothing		
No Flow	<u>✓</u>	<u>N/A</u>
Gas		
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS:

By Alan Kink Witness _____
Senior Lease Operator
(Position)

