

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 505 334-6178 FAX: (505) 334-617

(505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

			•	•		•			
Date of Test	8/2/	8/2/10 Operator		Energen Resources			API# 300	3003929891	
Property Name	e		LAKE 103	Locatio	n: Unit B	Section 24 To	ownship 32	Range 6	
Pressure (Shu	ut-in or Proc		and Number) Tubing	35 Interme	diate 🖊	Casing 3/	8 Bradenh	ead <u>Ø</u>	
OPEN	BRADENH	EAD AND	INTERMEDIA	TE TO ATMOSF	HERE IND	OIVIDUALLY FOR	15 MINUTES E	ACH	
<u>Time</u>	Bradenhead BH Casing Intermediate			Intermediate Intermediate Casing			Bradenhead Flowed	Intermediate Flowed	
5 minutes 10 minutes	Blowdown	Monitor 3/8 R/8	Monitor W/A	Blowdown	Monitor	Steady Flow Surges			
15 minutes 20 minutes 25 minutes	0	318				Down to Nothing No Flow Gas		NA	
30 minutes 5 minute SI						Gas and Water Water			
If bradenhe Clear 5 Minute Sh	F	vater, che resh radenhea	Sal	ty Intermediat	Sulfur		RECEIVE AUG 201	ED 0 51.3	
REMARKS:						FOR	OIL CONS. DIV DE	ST. 3	
By Ola Senior	n kirk	se C	Derato		iness				

(Position)