



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-23-2010 Operator Gregory Resources API #30-0 3930135

Property Name Carrizos Unit 6A Well No. 5 Location: Unit 1 Section 10 Township 32N Range 5W

Well Status (Shut-In or Producing) Initial PSI: Tubing 215 Intermediate n/a Casing 94 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>n/a</u>	<u>94</u>	<u>n/a</u>	<u>n/a</u>
10 min	<u>0</u>		<u>94</u>		
15 min	<u>0</u>		<u>94</u>		
20 min	<u>0</u>		<u>94</u>		
25 min	<u>0</u>		<u>94</u>		
30 min	<u>0</u>	<u>↓</u>	<u>94</u>	<u>↓</u>	<u>↓</u>

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	☒
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE n/a

REMARKS:

By Michael Howe
Sr. Lease Operator
(Position)

Witness

E-mail address

