



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-7-2010 Operator Energex API #30-0 39.30469 ✓

Property Name Carrizos 15A11 Well No. 15A11 Location: Unit P Section 15 Township 32N Range 05W ✓

Well Status (Shut-In or Producing) Initial PSI: Tubing 55 Intermediate Casing 116 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	BH	Int	Csg	Int	Csg
5 min	0		116		
10 min	0		116		
15 min	0		116		
20 min	0		116		
25 min	0		116		
30 min	0		116		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	NO	
Surges	NO	
Down to Nothing	NO	
Nothing	NO	
Gas	NO	
Gas & Water	NO	
Water	NO	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR 0 FRESH 0 SALTY 0 SULFUR 0 BLACK 0

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS: Braden head had 0 through the hole test

By [Signature] SS17
Lease operator
(Position)

Witness

E-mail address