

5053279207

Benson-Montlin-Greer

03:37:34 p.m

07-20-2010

1/1



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-0170 FAX: (505) 334-0170
<http://omnr.state.nm.us/ocd/District/District3.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/22/10 Operator Benson Montlin Greer API #30-0 39 82279Property Name EPCMU Well No. 18 Location: Unit P Section 13 Township 27N Range 1WWell Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate NA Casing 10 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			FLOW CHARACTERISTICS	
	BRADENHEAD			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>K</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE _____ BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

By Benson Montlin Greer

Witness _____

(Position)

E-mail address _____

