



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-19-2010 Operator Energen Resources API # 3003905546

Property Name W O HUGHES 3 Location: Unit L Section 8 Township 24 Range 3

(Well Name and Number)

Pressure (Shut-in or Producing) 115 Intermediate 160 Casing 160 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	Ø	160				Steady Flow	
10 minutes	Ø	160				Surges	
15 minutes	Ø	160				Down to Nothing	
20 minutes						No Flow	X
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI	Ø	160				Water	


If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead Ø Intermediate

REMARKS:

No pressure on bradenhead



By

[Signature]

Witness

Lease Operator

(Position)