



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/18 Operator Energen Resources API # 3003906492

Property Name JICARILLA 99 2 Location: Unit A Section 14 Township 26 Range 3
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 25 Intermediate N/A Casing 59 Bradenhead 6

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	0	59				Steady Flow		
10 minutes	0	61				Surges		
15 minutes	0	64				Down to Nothing	✓	
20 minutes	0	64				No Flow		
25 minutes	0	64				Gas	✓	
30 minutes	0	64				Gas and Water		
5 minute SI	0	64				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead -0- Intermediate _____

REMARKS:

Braden head valve shut in May 14th.
Perform test w/ inlet valve shut in @ Separator.
Braden head pressure after 5 minutes shut in is small
to measure.

By Ed. Edwards Witness _____
lease operator
(Position)

