

(Position)

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

			(000	2 00p.00 to u.	oro addito				
Date of Test	5/2	5 /21 /7010 Operator		Energen Resources			API# 30	# 3003906503	
Property Nan	ne	JICARILLA F 15			Location: Unit E Section 15			Range 5	
		(Well Name	e and Number)					· -	
Pressure (Sh	nut-in or Proc	ducing)	5 <u>—</u>		····	Casing	O Bradenl	nead <u>O</u>	
OPEI	N BRADENH	EAD AND	-	E TO ATMOSF		IVIDUALLY FOR	15 MINUTES I	EACH	
Bradenhead			ad	Intermediate			Bradenhead	Intermediate	
<u>Time</u>	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed	
5 minutes	0	0				Steady Flow			
10 minutes	$\frac{v}{v}$	0				Surges			
15 minutes	v	U				Down to Nothing			
20 minutes						No Flow			
25 minutes					_	Gas			
30 minutes					·	Gas and Water			
5 minute SI	0	0				Water			
If bradenho Clear 5 Minute S REMARKS:	F	resh _ radenhea	Salty		Sulfur	<u>ow:</u> Bla	nck		
		· <u>-</u>				, <u> </u>			
				<u> </u>					
вуЕ	rik Pe	tago	Eich P.	Staye Wit	ness				
	euse C	Pera	Eich P.	<i>J</i>					