

5053279207

Benson-Montlin-Greer

03 37:34 p.m

07-20-2010

1/1



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO DRAZOS ROAD
AZTEC NM 87410
(800) 334-6178 FAX: (800) 334-6170
<http://emnr.state.nm.us/od/District10/aztecdistrict.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/21/10 Operator Benson Montlin Greer API #30-0 39 23182

Property Name Mother Lode Well No. 1 Location: Unit 4 Section 3 Township 24N Range 2W

Well Status (Shut-In or Producing) Initial PSI: Tubing 22 Intermediate 1/A Casing 22 Bradenhead 5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			FLOW CHARACTERISTICS	
	BRADENHEAD			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg
TIME					
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					
				Steady Flow	
				Surges	
				Down to Nothing	
				Nothing <u>X</u>	
				Gas	
				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD _____

INTERMEDIATE _____

REMARKS:

By Benson Montlin Greer

Witness _____

(Position)

E-mail address _____

