

## NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test	7/16/2010		Operator		Energen Resources		ces A	API# 3003924291	
Property Nam		Vell Name	2 5 UT NP 106 and Number) Tubing	0			Section 26 To	ownship 32	
OPEN	N BRADENHE	AD AND	INTERMEDIA	TE TO	ATMOS	PHERE IND	IVIDUALLY FOR	15, MINUTES E	ACH
Time 5 minutes 10 minutes 15 minutes 20 minutes 25 minutes 30 minutes 5 minute SI	BH Blowdown  O  O  O  O  O  O  O  O  O  O  O  O  O	adenhea Casing Monitor 3/0 3/0 3/0 3/0 3/0 3/0 3/0	Intermediate Monitor		Intermediate lowdown		Steady Flow Surges Down to Nothing No Flow Gas Gas and Water Water	Flowed	Intermediate Flowed
If bradenhead flowed water, check all of the descriptions that apply below:  Clear Fresh Salty Sulfur  5 Minute Shut-in Bradenhead Intermediat  REMARKS:    Salty Sulfur RECEIVED   RECEIVE									
By Richa Leasa	ord Faire	bank For (Position			w	itness			