



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7/16/2010 Operator Energen Resources API # 3003925882

Property Name SAN JUAN 32 5 UNIT 17M Location: Unit N Section 26 Township 32 Range 6
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 40 Intermediate 0 Casing 240 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	240	0	0	240		
10 minutes	0	240	0	0	240		
15 minutes	0	240	0	0	240		
20 minutes	0	240	0	0	240		
25 minutes	0	240	0	0	240		
30 minutes	0	240	0	0	240		
5 minute SI	0	240	0	0	240		
						Steady Flow	
						Surges	
						Down to Nothing	
						No Flow	X
						Gas	X
						Gas and Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate 0

REMARKS:

By Richard Fairbanks Witness _____
Lease Operator
(Position)

