



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/21/10 Operator Energen Resources API # 3003926261

Property Name JICARILLA 97 6 Location: Unit D Section 7 Township 26 Range 3
(Well Name and Number)

Pressure (Shut-in or Producing) Producing Tubing 65 Intermediate N/A Casing 130 Bradenhead -0-

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	0	130				Steady Flow		
10 minutes	0	130				Surges		
15 minutes	0	130				Down to Nothing	✓	
20 minutes						No Flow		
25 minutes						Gas	✓	
30 minutes						Gas and Water		
5 minute SI	0	130				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead -0- Intermediate _____

REMARKS:

B. h. valve shut-in May 14th.

By Ed. Edwards

Witness _____

Lease operator

(Position)

