

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

			(• - • • • • • • • • • • • • • • • • • • •		,			
Date of Test	5-17	<u> </u>		Energen Resources			API#	3003926552	
Property Name	e	JICARILLA 96 2B			Location: Unit I Section 2		Township 26 Range 3		
		(Well Name	and Number)						
Pressure (Shu	ut-in or Proc	ducing	Tubing $\underline{\mathscr{S}}$	5 Interme	diate <u>///</u>	A Casing //	<u>5</u> Br	adenhead <u>O</u>	
OPEN	BRADENH	EAD AND	INTERMEDIA	TE TO ATMOSI	PHERE INC	DIVIDUALLY FOR	15 MINU	TES EACH	
	Bradenhead			Interme	diate]	Bradenhead Intermediate		
Time	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flow		
5 minutes			World	Biowdown	World	Steady Flow	,		
10 minutes	0	115				Surges	•		
15 minutes	D	115				Down to Nothing			
20 minutes		//)				No Flow	' レ		
25 minutes						Gas	3 /	<u> </u>	
30 minutes						Gas and Water	r	2031-1234	
5 minute SI		115				Water			
L			ck all of the de	escriptions tha	t apply bel	l <u>ow:</u>	ack	TEUEIVEI	
Clear	F	resh _	Salt	ty	Sulfur	Bla	ack 🔀	<u> </u>	
5 Minute Sh	iut-in B	radenhea	d	Intermediat				55/50SEIBITY	
REMARKS:	Br	aden 1	read si	rut in	May	14 th. 1	est or	n May 17	
					/				
зу <u>Е</u> Г.	Edwar	dr		Wi	tness	· · · · · · · · · · · · · · · · · · ·			
Lease	opera	tor							
	1	(Position	1)						