



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/20/10 Operator Energren Resources API # 3003926891

Property Name JICARILLA 96 7C Location: Unit K Section 1 Township 26 Range 3  
(Well Name and Number)

Pressure (Shut-in or Producing) Producing Tubing 76 Intermediate N/A Casing 99 Bradenhead 11

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	0	99				Steady Flow	✓	
10 minutes	0	105				Surges		
15 minutes	0	107				Down to Nothing		
20 minutes	0	107				No Flow		
25 minutes	0	107				Gas	✓	
30 minutes	0	107				Gas and Water		
5 minute SI	10	107				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear ✓ Fresh        Salty        Sulfur        Black       

5 Minute Shut-in Bradenhead 10 Intermediate       

REMARKS:

B.h. valve shut-in may 14th.

By Ed. Edwards

Witness       

Lease operator

(Position)

