

## **NEW MEXICO ENERGY, MINERALS** AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410

(505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

## **BRADENHEAD TEST REPORT**

			(Subm	it 2 copies to at	ove addre	ss)		•
Date of Test	5-2	5 - 20 - 2010 Operator		r Energ	Energen Resources			3905218
Property Name		LINDRIT	H UNIT 56	Locatio	Location: Unit I Section 31		ownship 24	Range 2
		(Well Name	and Number)	<del></del>	<del></del>			
Pressure (Shu	t-in or Proc	ducing)	Tubing _	85 Interme	diate	Casing <u>7</u>	> Bradenh	ead <u>Ø</u>
OPEN	BRADENH	EAD AND	INTERMEDIA	TE TO ATMOSF	HERE IND	IVIDUALLY FOR	15 MINUTES E	ACH
Γ	Bradenhead			Intermediate			Rradenhead	Intermediate
<u>Time</u>	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	8	95				Steady Flow		
10 minutes	<u> </u>	95				Surges		
15 minutes	8	95				Down to Nothing		
20 minutes						No Flow	<u>×</u>	
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI	Ø	95			-	Water		
<u>lf bradenhea</u>	ad flowed v	vater, che	ck all of the d	lescriptions tha	t apply bel	ow:		
Clear	F	resh _	Sa	Ity	Sulfur	Bla		
5 Minute Sh	u <b>t-in</b> B	radenhea	d <u>6</u>	Intermediat			REC	123456 A EIVED 101111 2010
REMARKS:							25.65 <b>DUN</b>	2010
							OIL CONS.	DIV. DIST. 3 ्छें/
							OIL CONS.	~[c]*
A	1						202	618111
Ву	# 1			Wi	tness			
	1 /	•	Operator					
		(Position	1) ້					