



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-21-2010 Operator Energen Resources API # 3003905308

Property Name LINDRITH UNIT 34 Location: Unit B Section 25 Township 24 Range 3
(Well Name and Number)

Pressure (Shut-in or Producing) 80 Tubing 80 Intermediate 80 Casing 80 Bradenhead 80

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>80</u>	<u>80</u>				Steady Flow		
10 minutes	<u>80</u>	<u>80</u>				Surges		
15 minutes	<u>80</u>	<u>80</u>				Down to Nothing		
20 minutes						No Flow	<u>X</u>	
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI	<u>80</u>	<u>80</u>				Water		


If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur

5 Minute Shut-in Bradenhead 80 Intermediate 80

REMARKS:

No pressure on braden head



By

[Signature]

Witness

Lease Operator

(Position)