NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-21-2010 **Operator** Energen Resources **API #** 3003905574

Property Name LINDRITH UNIT NP 68 **Location:** Unit G Section 7 Township 24 Range 2

(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 95 Intermediate _____ Casing 115 Bradenhead 20

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead: BH Blowdown	Bradenhead: Casing Monitor	Bradenhead: Intermediate Monitor	Intermediate: Intermediate Blowdown	Intermediate: Casing Monitor
5 minutes	Ø	115			
10 minutes	Ø	115			
15 minutes	Ø	115			
20 minutes	Ø	115			
25 minutes	Ø	115			
30 minutes	Ø	115			
5 minute SI	15	115			

	Bradenhead Flowed	Intermediate Flowed
Steady Flow		
Surges		
Down to Nothing	X	
No Flow		
Gas	X	
Gas and Water		
Water		

RECEIVED JUN 2010 OIL CONS. DIV. DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 15 Intermediat _____

REMARKS: 15 psi on bradenhead after 5 minute SI

By [signature] **Witness** _____

Lease Operator

(Position)

NMOCD Test Area: C 735