



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-21-2010 Operator Energen Resources API # 3003908074

Property Name LINDRITH UNIT 60 Location: Unit P Section 25 Township 24 Range 3
(Well Name and Number)

Pressure (Shut-in or Producing) 80 Intermediate 45 Casing 15 Bradenhead 15

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>	<u>44</u>				<u>X</u>	
10 minutes	<u>0</u>	<u>43</u>					
15 minutes	<u>0</u>	<u>41</u>					
20 minutes	<u>0</u>	<u>41</u>					
25 minutes	<u>0</u>	<u>40</u>				<u>X</u>	
30 minutes	<u>0</u>	<u>38</u>					
5 minute SI	<u>0</u>	<u>39</u>					
						Steady Flow	
						Surges	
						Down to Nothing	
						No Flow	
						Gas	
						Gas and Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 8 Intermediate

REMARKS:

Light steady flow from braden head
8 psi after 5 minute SI



By [Signature]
Lease Operator
(Position)

Witness