NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-21-2010 **Operator** Energen Resources **API #** 3003920638

Property Name LINDRITH UNIT 76 **Location:** Unit K Section 25 Township 24 Range 3

(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 95 Intermediate _____ Casing 95 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor
5 minutes	Ø	95			
10 minutes	Ø	95			
15 minutes	Ø	95			
20 minutes					
25 minutes					
30 minutes					
5 minute SI	Ø	95			

	Bradenhead Flowed	Intermediate Flowed
Steady Flow		
Surges		
Down to Nothing		
No Flow	Y	
Gas		
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead Ø Intermediat _____

REMARKS: No Pressure on bradenhead

RECEIVED
JUN 2010
OIL CONS. DIV. DIST. 3

By _____ **Witness** _____

_____
(Position)

NMOCD Test Area: C 716