



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-21-2010 Operator Energen Resources API # 3003923817

Property Name LINDRITH UNIT NP 114 Location: Unit 0 Section 7 Township 24 Range 2
(Well Name and Number)

Pressure (Shut-in or Producing) 50 Tubing 50 Intermediate Casing 100 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>0</u>	<u>100</u>						
10 minutes	<u>0</u>	<u>100</u>						
15 minutes	<u>0</u>	<u>100</u>						
20 minutes								
25 minutes								
30 minutes								
5 minute SI	<u>0</u>	<u>100</u>						

Steady Flow		
Surges		
Down to Nothing		
No Flow	<u>X</u>	
Gas		
Gas and Water		
Water		


If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate

REMARKS:

No pressure on Bradenhead



By

[Signature]

Witness

Lease Operator

(Position)