## RECEIVED

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

AUG 05 2010

| Sundry Notices and Reports on Wells   | Farmington Field Office<br>Bureau of Land Management   |
|---|--|
| . Type of Well GAS  | 5. Lease Number<br>SF-078498<br>6. If Indian, All. or<br>Tribe Name  |
| Name of Operator  CONOCOPHILLIPS COMPANY  RECEIVED 6  MG 2010   | 7. Unit Agreement Name<br>San Juan 28-7 Unit   |
| . Address & Phone No. of Operator   | 8. Well Name & Number<br>San Juan 28-7 Unit 1  |
| PO Box 4289, Farmington, NM 87499 (505) 326-9700  | 9. API Well No.  |
| . Location of Well, Footage, Sec., T, R, M  | 30-039-07274<br>10. Field and Pool   |
| Surf: Unit A (NENE), 660' FNL & 660' FEL, Section 33, T28N, R7W, NMPM   | Blanco PC/Blanco MV  |
|   | 11. County and State<br>Rio Arriba Co., NM   |
| Z. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT Type of Submission  Type of Action  Type of Action  Abandonment Recompletion Recompletion Plugging Non-Routine Fractu Casing Repair Water Shut off Conversion to Inject | X Other – <u>Cathodic Protection</u>   |
| 3. Describe Proposed or Completed Operations  |  |
| attached is a drawing of the placement of the cathodic protection ground bed, rectific<br>AC  | er and cable for the subject well. CEPTED FOR RECORD  AUG 0 8 2010   |
|   | AMINGTON FIELD OFFICE    The Charles   Section   Section |
| This space for Federal or State Office use)  PPROVED BY   | Date   |

MMOCD K


PC



## San Juan 28-7 Unit 1 & 191E

Section 33, T28N, R7W, N.M.P.M., Rio Arriba County, NM





Run new positive cable from existing rectifier to new already drilled ground bed, and plow negative to #191E wellhead at lengths listed below.

Positive: 203'

Negative: 730"

Total Ditch: 933'

By: Steven Gillette Date: 5/25/10