



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-29-10 Operator ConocoPhillips API #30-0 39-24807
Property Name San Juan 29-6-40 Well No. 301 Location: Unit Section 2 Township 29 Range 6
Well Status (Shut-In or Producing) Initial PSI: Tubing 313 Intermediate 0 Casing 113 Bradenhead 40

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>light blow</u>	<u>0</u>	<u>113</u>		
10 min	<u>"</u>	<u>0</u>			
15 min	<u>"</u>	<u>0</u>			
20 min	<u>"</u>	<u>0</u>			
25 min	<u>"</u>	<u>0</u>			
30 min	<u>"</u>	<u>0</u>	<u>118</u>		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	<u>/</u>	<u>gas</u>
Surges		
Down to Nothing		<u>/</u>
Nothing		
Gas	<u>/</u>	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 1.5 INTERMEDIATE 0

REMARKS: Had blow to light blow just a seconds - blew light
for whole 30 minutes
light diff from intermediate when opened

By Ken N. L.
SNO Specialist
(Position)

Witness Monica Kuehling

E-mail address