



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7/13/10 Operator Energen Resources API # 3003924295

Property Name SAN JUAN 32 5 UNIT 102 Location: Unit K Section 24 Township 32 Range 6
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 460 Intermediate N/A Casing 540 Bradenhead


OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>0</u>	<u>540</u>	<u>N/A</u>	<u>N/A</u>		Steady Flow		
10 minutes	<u>0</u>	<u>540</u>				Surges		
15 minutes	<u>0</u>	<u>540</u>				Down to Nothing		
20 minutes						No Flow	<u>✓</u>	<u>N/A</u>
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI						Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur

5 Minute Shut-in Bradenhead 0 Intermediate N/A



REMARKS:

By Alan Kirk
Senior Lease Operator
(Position)

Witness