

SAN JUAN 28-4 UNIT #37

Burlington Resources Oil & Gas Company, LP

Most Recent Job

Jobs

Job Category	Primary Job Type	Secondary Job Type	Actual Start Date	End Date
WELL INTERVENTION	CASING REPAIR		9/21/2010	10/1/2010

Well Config: - Original Hole, 11/24/2010 7:30:00 AM

