## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

## RECEIVED

AUG 1 1 2010

	Sundry Notices and Reports on Wells	Farmington Field Office Bureau of Land Manageme	ont
1.	Type of Well GAS		
2.	BURLINGTON \\( \text{\cong} \) OIL CONS DIVE	7. Unit Agreement Huerfano Unit	t Nam
3.	HESCURCES OIL & GAS COMPANY LP	3 20/ 30 Well Name & N Huerfano Unit (	
	PO Box 4289, Farmington, NM 87499 (505) 326-9700	9. API Well No.	
- 4.	Location of Well, Footage, Sec., T, R, M	30-045-06020	
		10. Field and Pool	
Sur	irf: Unit P (SESE), 990' FSL & 990' FEL, Section 4, T26N, R10W, NMPM	West Kutz PC 11. County and Star San Juan Co., N	
12.	CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, RE Type of Submission Type of Action  Notice of Intent Abandonment Change of Pl.  Recompletion New Construt  X Subsequent Report Plugging Non-Routine  Casing Repair Water Shut of Final Abandonment Altering Casing Conversion to	lans X Other – Cathodic Protection Fracturing	rotection
	. Describe Proposed or Completed Operations		
13.			
13.	Attached is a drawing of the placement of the cathodic ground bed, rectifier	and cable for the subject well.	
14.	gned Mandal Place Brandie Blakley Title Staff		1-1 <u>c</u>
14.	1. I hereby certify that the foregoing is true and correct.		1-10


N/

NMOCD



## Huerfano Unit 224, NP 303 & 62

Section 4, T26N, R10W, N.M.P.M., San Juan County, NM



G.B. #1 △

Drill new ground bed approximately 114' South of #224 wellhead at staked location. Run new positive cable from existing rectifier to new ground bed #3 at length listed below.

Positive: 27'

Total Ditch: 27'

By: Randy Smith Date: 5/25/10