



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-8-10 Operator ElmRidge API #30-0 39-21667
Property Name Candado Well No. 21 Location: Unit Section 4 Township 26 Range 7
Well Status(Shut-In or Producing) Initial PSI: Tubing 143 Intermediate NA Casing 253 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min	0	NA	253		NA	Steady Flow	NA
10 min	0		253			Surges	
15 min	0		253			Down to Nothing	
20 min	0		253			Nothing	X
25 min	0		253			Gas	
30 min	0		253			Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE


BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

By

Donny Snell
Pumper
(Position)

Witness



E-mail address