



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-21-2010 Operator Energen Resources API # 3003906608

Property Name JICARILLA 119 N 7 Location: Unit A Section 8 Township 26 Range 4  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 35 Intermediate        Casing 80 Bradenhead TSTM

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	0	80				Steady Flow		
10 minutes	0	80				Surges		
15 minutes	0	80				Down to Nothing	✓	
20 minutes						No Flow		
25 minutes						Gas	✓	
30 minutes						Gas and Water		
5 minute SI	0	80				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear        Fresh        Salty        Sulfur        Black       

5 Minute Shut-in Bradenhead 0 Intermediate       

REMARKS:

To small to measure pressure.

By Alex Hower

Witness       

Field Operator

(Position)

