



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-19-2010 Operator Energen Resources API # 3003907134

Property Name JICARILLA 119 N 10 Location: Unit L Section 7 Township 26 Range 4  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 100 Intermediate        Casing 115 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>0</u>	<u>115</u>				Steady Flow		
10 minutes	<u>0</u>	<u>115</u>				Surges		
15 minutes	<u>0</u>	<u>115</u>				Down to Nothing		
20 minutes	<u>0</u>	<u>115</u>				No Flow	<input checked="" type="checkbox"/>	
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI	<u>0</u>	<u>115</u>				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear        Fresh        Salty        Sulfur       

5 Minute Shut-in Bradenhead 0 Intermediate       

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Alex Huang  
Field Operator  
(Position)

Witness \_\_\_\_\_

