



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-19-2010 Operator Energen Resources API # 3003922274

Property Name JICARILLA 152 W 5 Location: Unit G Section 7 Township 26 Range 5  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 55 Intermediate      Casing 60 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Steady Flow	Surges	Down to Nothing	No Flow	Gas	Gas and Water	Water
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor							
5 minutes	0	60										
10 minutes	0	60										
15 minutes	0	60										
20 minutes									✓			
25 minutes												
30 minutes												
5 minute SI	0	60										

If bradenhead flowed water, check all of the descriptions that apply below:

Clear      Fresh      Salty      Sulfur     

5 Minute Shut-in Bradenhead 0 Intermediate     

REMARKS:



By Alex Howey  
Field Operator  
(Position)

Witness