



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

**BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 05-25-10 Operator ELMRIDGE RESOURCES API #30-0 39-24921

Property Name RINCON Well No. 19-3 Location: Unit 2 Section 19 Township 23 Range 6

Well Status(Shut-In or Producing) Initial PSI: Tubing 45 Intermediate 0 Casing 60 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME	<u>0</u>		<u>60</u>		<u>60</u>
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					


FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<input checked="" type="checkbox"/>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:



By

Oscar Poyar  
Pumper  
(Position)

Witness \_\_\_\_\_

E-mail address \_\_\_\_\_