



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT


(submit 1 copy to above address)

Date of Test 10/26/10 Operator Black Hills Gas Res. API #30-0 39-25855
Property Name Jicarilla 459-20P Well No. 12 Location: Unit 0 Section 20 Township 30N Range 3W
Well Status (Shut-In or Producing) Initial PSI: Tubing 40 Intermediate N/A Casing 32 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>32</u>		
10 min	<u>0</u>		<u>32</u>		
15 min	<u>0</u>		<u>32</u>		
20 min	<u>0</u>		<u>32</u>		
25 min	<u>0</u>		<u>32</u>		
30 min	<u>0</u>		<u>32</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	☒
Gas	
Gas & Water	
Water	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

no water or pressure on bradenhead

By Kirt D. Vincent
Lease operator
(Position)

Witness _____

E-mail address Kirt.Vicenti@bhep.com