



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10/12/10 Operator Blackhills Gas Res. API #30-0 39-26229


Property Name Jicarilla 460 Well No. 2 Location: Unit M Section 21 Township 30N Range 3W

Well Status (Shut-In or Producing) Initial PSI: Tubing 32 Intermediate N/A Casing 25 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>25</u>		
10 min	<u>0</u>		<u>25</u>		
15 min	<u>0</u>		<u>25</u>		
20 min	<u>0</u>		<u>25</u>		
25 min	<u>0</u>		<u>25</u>		
30 min	<u>0</u>		<u>25</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing ☒	
Gas	
Gas & Water	
Water	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

no water or pressure on bradenhead.

By Kirt D. Vicenti
Lease operator
(Position)

Witness _____

E-mail address Kirt.Vicenti@bhep.com