

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(606) 334-6176 FAX: (606) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-10-10 Operator Black HIIIS GK API #30-0 26658									
Property Name 29-2-/7 Well No. 2 Location: Unit F Section 17 Township 291/Range 020									
Well Status(Shut-In or <u>Reoducing</u>) Initial PSI: Tubing 60 Intermediate Casing 6 Bradenhead 0									
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH									
Testing	PRESSURE esting Bradenhead INT BH Int Csg Int				RM Csg	BR.	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE		
TIME	6		6		Cog	Steady Flow	·		
10 min	0		6			Surges	1		
15 min	0		6			Down to Nothing			
20 min	0		6			Nothing			
25 min	0		6			Gas			
30 min	0		6			Gas & Water			
						Water		01-123	
If bradenhead flowed water, check all of the descriptions that apply below:									
CI	LEAR_	F	RESH_	S	ALTY	SULFURBI	LACK	RECEIVED	
If bradenhead flowed water, check all of the descriptions that apply below: CLEAR FRESH SALTY SULFUR BLACK RECEIVED NOW 2010 5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE OIL CONS. DIV. DIST. 3 REMARKS:									
REMARKS:									
			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,						
By Judson Valle					Witness				
(Position)									
By Judsia Value Witness Witness Permail address Judduc & B/IEDarn. Om									