



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 8-23-10 Operator Energen Resources API # 3003907763

Property Name SAN JUAN 30 4 UNIT 3 Location: Unit A Section 29 Township 30 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 175 Intermediate w/A Casing 190 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Steady Flow	Surges	Down to Nothing	No Flow	Gas	Gas and Water	Water
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor							
5 minutes	<u>no Blow</u>	<u>190</u>		<u>w/A</u>								
10 minutes	<u>no Blow</u>	<u>190</u>		<u>w/A</u>								
15 minutes	<u>no Blow</u>	<u>190</u>		<u>w/A</u>								
20 minutes												
25 minutes												
30 minutes												
5 minute SI												


Bradenhead Flowed	Intermediate Flowed
	<u>w/A</u>
	<u>w/A</u>
	<u>w/A</u>
<u>X</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____

5 Minute Shut-in Bradenhead 0 Intermediate w/A

REMARKS:



By

Jeff Graham
Lease Operator
(Position)

Witness