

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 7-11-10 Operator Dugan Production Corp API # 30-039-23048  
Property Name Sapp C Well No. 3 Location: Unit 0 Section 5 Township 23N Range 07W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 48 Intermediate 0 Casing 50 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE						FLOW CHARACTERISTICS		
	Bradenhead			Interm			BRADENHEAD	INTERMEDIATE	
	BH	Int	Csg	Int	Csg				
5 minutes	<u>0</u>		<u>50</u>					Steady Flow	
10 minutes								Surges	
15 minutes								Down to Nothing	
20 minutes	<u>0</u>		<u>50</u>					<u>Nothing</u>	
25 minutes								Gas	
30 minutes								Gas & Water	
								Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN

BRADENHEAD

0

INTERMEDIATE

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By

Bolero

Witness

Switcher

(Position)

