

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emrmd.state.nm.us/ocd/District_III/3district.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 6-7-10 Operator Dugan Production Corp API # 30-039-25745
Property Name Mona Lisa Well No. 2 MV Location: Unit J Section 14 Township 26N Range 07W
Well Status(Shut-In or Producing) Initial PSI: Tubing 140 Intermediate Casing 200 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead		Interm			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
5 minutes	0		200			Steady Flow	
10 minutes	0		200			Surges	
15 minutes	0		200			Down to Nothing	
20 minutes						Nothing	✓
25 minutes						Gas	
30 minutes						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0

INTERMEDIATE _____

REMARKS:

By Ben Honah #31
Switcher
(Position)

Witness _____

